



| Printer Identifier | Toshiba e-STUDIO520 | | | | | | |
|-----------------------------|--|--|--|--|--|--|--|
| Cartridge Type | Separate toner and drum | | | | | | |
| Cartridge Identifiers | Toshiba T-6000 | | | | | | |
| Test Methodology | ISO/IEC 19752 2004-06-15 | | | | | | |
| Test Contact Information | QualityLogic, Inc. 5401 Tech Circle Moorpark, CA 93021 | | | | | | |

Declaration of Yield:

Toner Cartridge Yield when tested in Toshiba e-STUDIO520:

Using the test suite defined in ISO/IEC 19752 provides the following results:

Average K (Black) Cartridge Yield – Up to 76,178 standard pages

Values obtained by continuous printing. Declared yield values in accordance with ISO/IEC 19752

| Using 19752 Test Suite | | | | | | | | |
|------------------------|-----------|--------------------|----------------------------------|------------------------------------|----------------------------------|--|--|--|
| Cartridge Identifier | Color | Average (pages) | Standard Deviation (pages) | 90% Lower Confidence (pages) | Number used in calculations/test | | | |
| Toshiba T-6000 | K (Black) | 79,333 | 5,088 | 76,178 | 9/12 | | | |



Test Information

| Date Tested | August 24, 2007 to September 17, 2007 | | | | | |
|-------------------------------|--|--|--|--|--|--|
| Type of Cartridge | Separate toner and drum | | | | | |
| Shake procedure used | None | | | | | |
| Required Maintenance | A periodic maintenance is required by a qualified service technician. | | | | | |
| Clean procedure used | None. There is no cleaning procedure in the Toshiba e-STUDIO520 "Operator's Manual for Basic Function". | | | | | |
| End Of Life Criteria | This printer has Toner Out which stops printing. Whichever came first, either Toner Out or Fade, was used as the EOL criteria. | | | | | |
| Print mode | Continuous | | | | | |
| Number of printers used | 3 | | | | | |
| Media used | Xerox Business 4200, 92 Brightness 20lb. weight | | | | | |
| Paper Size | Letter | | | | | |
| Paper feed orientation | Portrait | | | | | |
| Computer model | Hewlett-Packard Compaq d220 MT | | | | | |
| CPU | 2.4 GHz. Celeron | | | | | |
| Memory | 512 MB | | | | | |
| Interface | Network interface using TCP/IP. | | | | | |
| Operating system | Microsoft Windows XP SP2 | | | | | |
| Driver version | Driver was obtained from printer via network. Driver version = 4.4.51.0 | | | | | |
| Application software | QualityLogic PageServe using Adobe Reader 8.0 | | | | | |
| Test Suite Version | Mono Laser - ISO/IEC 19752 (2004-06-15) | | | | | |
| Print Method/Captured File | A captured print file was used. Footer and page count information was included on the printed output. | | | | | |
| Power on off each day (Y/N) | No | | | | | |



Summary Table

| Cartridge Serial | Printer Serial | Temperature | | | Humidity | | | Cartridge | Used in | EOL ¹ |
|---------------------|----------------|-------------------|------------------|------------------|-------------------|------------------|------------------|-----------|-------------|------------------|
| | | °C | | | % | | | Yield | Calculation | |
| | | Avg. ² | Max ³ | Min ³ | Avg. ² | Max ³ | Min ³ | Pages | (Yes/No) | |
| QLI1 | C7CZ22745 | 23.1 | 23.7 | 22.5 | 49.8 | 54.0 | 45.7 | 78,350 | Yes | Toner Out |
| QLI5 | C7CZ22745 | 23.8 | 24.7 | 23.0 | 49.5 | 56.0 | 42.6 | 79,210 | Yes | Toner Out |
| QLI8 | C7CZ22745 | 23.9 | 24.4 | 23.0 | 48.2 | 52.3 | 44.1 | 80,800 | Yes | Toner Out |
| QLI2 | CZC722754 | 23.3 | 24.7 | 22.5 | 49.5 | 54.0 | 42.6 | 83,478 | Yes | Toner Out |
| QLI6 | CZC722754 | 23.8 | 24.5 | 23.0 | 49.5 | 56.0 | 43.6 | 85,886 | Yes | Toner Out |
| QLI9 | CZC722754 | 23.8 | 24.4 | 23.5 | 50.8 | 54.2 | 44.1 | 85,569 | Yes | Toner Out |
| QLI3 | CZC722747 | 23.1 | 23.7 | 22.5 | 49.9 | 54.0 | 45.7 | 71,800 | Yes | Toner Out |
| QLI4 | CZC722747 | 23.8 | 24.7 | 23.0 | 49.5 | 56.0 | 42.6 | 73,942 | Yes | Toner Out |
| QLI7 | CZC722747 | 23.9 | 24.4 | 23.0 | 48.2 | 52.3 | 44.1 | 74,958 | Yes | Toner Out |

Notes:

No defective cartridges or printers were encountered during testing.

This printer is a replenishment system. The original cartridges were consumed before testing started.

Comments:

All printers were supplied by Toshiba.

All consumables were acquired by QualityLogic.

¹ Depletion in this column indicates that the cartridge was used to deplete other cartridges but was not completed to EOL.

Averages are for the complete test cycle of the cartridge.
 Maximum and minimum averages are the averages of all four consecutive readings, per the ISO standard.